BranchMaster[™] Manifolds





80



BranchMaster[™]

³/₄" Female Sweat Branches 1¹/₄" Male Sweat × 1¹/₄" Male Sweat Trunk

- Branches are 4" on-center
- 1¼" Type L copper trunk
- Press-fitting compatible



Item No	Branch Qty	Branches	Pkg	Min Qty	Case Qty
67745L-08334	8	³ ⁄4" female sweat	В	1	5

BranchMaster[™] Manifold Endpiece

- 1" Type L copper trunk
- 1/8" FIP and 1/2" FIP branches
- Outlets connect to gauges, valves or service points
- · Perfect for radiant heat manifold application

Item No	Branch Qty	Trunk Ends	Pkg	Min Qty	Case Qty
677-11	2	1" female sweat × spin closed	В	1	10
677-116	2	11/2" female sweat × spin closed	В	1	10
677-117	2	2" female sweat × spin closed	В	1	10



677-11