


Full-Slip Repair Couplings

Sweat or Compression Connection

- 1/2" and 3/4" full-slip copper repair couplings
- Perfect for repair of cold and hot water lines
- Sweat and compression models



600-206



600-206C

Item No	Slips Over	Length	NO LEAD	Pkg	Min Qty	Case Qty
SWEAT						
600-203	1/2" CTS	3"	✓	B	50	500
600-206	1/2" CTS	6"	✓	B	25	250
600-206PK	1/2" CTS	6"	✓	C*	10	10
600-212	1/2" CTS	12"	✓	B	50	50
600-212PK	1/2" CTS	12"	✓	C*	10	10
600-303	3/4" CTS	3"	✓	B	25	250
600-306	3/4" CTS	6"	✓	B	50	50
600-306PK	3/4" CTS	6"	✓	C*	10	10
600-312	3/4" CTS	12"	✓	B	50	50
600-312PK	3/4" CTS	12"	✓	C*	10	10
COMPRESSION						
600-206C	1/2" CTS	6"		B	25	25
600-206CPK	1/2" CTS	6"		C*	10	10
600-212C	1/2" CTS	12"		B	25	25
600-212CPK	1/2" CTS	12"		C*	10	10
600-306C	3/4" CTS	6"		B	25	25
600-306CPK	3/4" CTS	6"		C*	10	10
600-312C	3/4" CTS	12"		B	25	25
600-312CPK	3/4" CTS	12"		C*	10	10
LEAD-FREE COMPRESSION						
600-G212CPK	1/2" CTS	12"	✓	C*	10	10
600-G312CPK	3/4" CTS	12"	✓	C*	10	10

Plated Stub Out Sleeves

Nickel-Plated Copper

- Slides over 1/2" or 3/4" CTS stub outs
- 12" long – can be cut to custom lengths

Item No	Slips Over	Length	Pkg	Min Qty	Case Qty
600-212N	1/2" CTS	12"	B	25	25
600-312N	3/4" CTS	12"	B	25	25



600-212N

SUPPLY

DRAINAGE

SUPPORT

APPENDIX