



Pressure Temperature Chart

R22 PSIG	Saturation Temperature	R410a PSIG
49	25	87
50	26	89
51	27	91
52	28	93
54	29	95
55	30	97
56	31	99
58	32	101
59	33	103
60	34	105
62	35	107
63	36	109
64	37	111
65	38	114
67	39	116
69	40	118
70	41	120
72	42	123
73	43	125
75	44	127
76	45	130
78	46	132
79	47	135
81	48	137
82	49	140
84	50	142
86	51	145
87	52	147
89	53	150
91	54	153
93	55	156
94	56	158
96	57	161
98	58	164
100	59	167
102	60	170
104	61	173
105	62	175
107	63	178
109	64	182
111	65	185
113	66	188
115	67	191
117	68	194
119	69	197
121	70	200
124	71	204
126	72	207
128	73	210
130	74	214
132	75	217

R22 PSIG	Saturation Temperature	R410a PSIG
135	76	221
137	77	224
139	78	228
141	79	231
144	80	235
146	81	239
148	82	242
151	83	246
153	84	250
156	85	254
158	86	258
161	87	261
163	88	265
166	89	269
168	90	274
171	91	278
173	92	282
176	93	286
179	94	290
182	95	294
185	96	299
187	97	303
190	98	308
193	99	312
196	100	316
199	101	321
202	102	326
205	103	330
208	104	335
211	105	340
214	106	344
217	107	349
220	108	354
223	109	359
226	110	364
230	111	369
232	112	374
236	113	379
239	114	385
243	115	390
246	116	395
250	117	401
253	118	405
256	119	411
260	120	417
264	121	423
267	122	428
271	123	434
274	124	440
278	125	445
282	126	451