

Expandable Stick Meters

HS33, HS35, HS36

The Perfect Fit for Most HVACR Jobs.

The HS30 Series meters are some of the most versatile HVACR meters around. Already packed with the measurements HVACR pros need, they also connect directly into Fieldpiece Accessory Heads, so techs don't need extra meters for additional measurements.

- Ruggedized rubber corners
- Magnetic strap for hands-free testing
- High voltage indicators
- Lead storage
- Non-contact voltage
- Capacitance
- MIN/MAX and Hold buttons to record measurements
- Low ohms for motor windings
- Fast, accurate temps

Included

- 400A AC Amp Clamp Accessory – ACH4
- Type K Thermocouple – ATB1
- Deluxe Silicone Test Leads – ADLS2
- Alligator Clip Lead Extensions – ASA2
- 4-Pocket Meter Case – ANC1
- Velcro Strap



HS36



HS33



HS35



Original HS26 Also Available
See Fieldpiece.com for details



HS33	HS35	HS36	Function	Range	Resolution
Manual	Auto	Auto	Ranging		
2000	4000	4000	Counts		
Average	Average	True RMS	AC Conversion		
	●	●	Backlight		
	●	●	Bar Graph		
●	●	●	VAC	200m	1.2% + 5/0.1m
	●	●		2000m	1.5% + 5/1m
	●	●		40	1.5% + 5/0.01
●	●	●		200	1.5% + 5/0.1m
●	●	●		600	2% + 5/1
●	●	●	VDC	200m	0.5% + 2/0.1 m
●	●	●		2000m	0.5% + 2/1m
	●	●		20	0.5% + 2/0.01
●	●	●		200	0.5% + 2/0.1
	●	●		600	0.5% + 2/1
●	●	●	AAC	20	2.7% + 7/0.1
●	●	●		100	3.7% + 8/0.1
●	●	●		400	5.0% + 10/1
	●	●	ADC	400μ	1% + 2/0.1 μ
	●	●		4000μ	1% + 2/1 μ
●	●	●	°F	200° F	1° F/0.1
	●	●		1000° F	1° F/1
●	●	●	MFD	200	3% + 5/0.1m
●	●	●	Hi-V Indicator		>30V
●	●	●	NCV		>24VAC
●	●	●	Ohms	200	1% + 4/0/1
	●	●		4K	1% + 4/1
	●	●		40K	1% + 4/10
●	●	●		200K	1% + 4/100
	●	●		4M	1.5% + 4/1K
	●	●		20M	3% + 5/10K
●	●	●	Continuity		
●	●	●	Diode		
	●	●	HZ		

● With ACH4 clamp head, ● LED and beeper, ● Range is 40XX, not 20XX

Temperature accuracies shown are after simple field calibration

Gun Style IR Thermometer with Laser

SIG1

The SIG1 takes accurate surface temperatures. The narrow 10:1 field of view allows techs to target smaller areas.

- 10:1 field of view
- Select °F or °C
- Range: -22°F to 1022°F



All Fieldpiece thermocouples work with Fieldpiece meters that take temperature.



ATC1



ATC2



ATC1R

Infrared Surface Temperature with Laser

ATIR3

Walk from freezer to roof without losing accuracy.

- Measure temperature without contact
- 8:1 field of view
- Select °F or °C



IR Thermometer with Laser

SIR2

Ergonomic pocket IR with laser.

- 6:1 field of view
- MIN/MAX automatic data hold
- Select °F or °C




Shirt Pocket IR Thermometer

SIP3

Great for quick air register temps.

- 1:1 field of view
- 1° resolution in °F and °C
- Auto-power-off



Model	Description	MAX° F PROBE TEMP
ATBI	Bead type standard	400
ATAI	Bead type with alligator	400
ATAFI	HI-temp bead type with alligator	900
ATWBI	Wet bulb (sock) with alligator	200
ATCIR	Pipe clamp-refrig. (1/8-to 3/4")	257
ATC1	Pipe clamp (3/8-to 1 3/8")	257
ATC2	Pipe clamp (up to 2 1/4")	180
ATEXT10	10' extension cables	400
ATFI	Stainless steel, 6" rod for fluids	1500
ATRI	4.5- piercing rod with handle	1500
ATSI	Disk shaped for grilles	1500

IR Pocket Thermometer with LED Flashlight

SIL2

Great accuracy and a built-in LED flashlight.

- 1:1 field of view
- Select °F or °C
- Automatic data hold

