

SUPPLY

DRAINAGE

SUPPORT

APPENDIX



643X2



643X202

PowerPEX™

Copper Straight Adapter

Male Sweat × PEX

• One-piece solid copper

Item No	Description	Pkg	Min Qty	Case Qty
643X11	3/8" F1807 × 3/8" MSWT	B	100	1000
643X1	3/8" F1807 × 1/2" MSWT	B	100	1000
643X1PK2	3/8" F1807 × 1/2" MSWT, 2/bag	C*	20	20
643X2	1/2" F1807 × 1/2" MSWT	B	100	1000
643X2PK2	1/2" F1807 × 1/2" MSWT, 2/bag	C*	20	20
643X202	1/2" F1807 × 1/2" MSWT, 2" long	B	50	500
643X32	1/2" F1807 × 3/4" MSWT	B	50	500
643X32PK2	1/2" F1807 × 3/4" MSWT, 2/bag	C*	10	10
643X23	3/4" F1807 × 1/2" MSWT	B	50	100
643X23PK2	3/4" F1807 × 1/2" MSWT, 2/bag	C*	20	20
643X3	3/4" F1807 × 3/4" MSWT	B	50	500
643X3PK2	3/4" F1807 × 3/4" MSWT, 2/bag	C*	10	10
643X43	3/4" F1807 × 1" MSWT	B	25	250
643X34	1" F1807 × 3/4" MSWT	B	25	250
643X4	1" F1807 × 1" MSWT	B	25	250



NO LEAD

PowerPEX™

Copper Straight Adapter

Female Sweat × PEX

• One-piece solid copper



644X2

Item No	Description	Pkg	Min Qty	Case Qty
644X1	3/8" F1807 × 1/2" FSWT	B	100	1000
644X1PK2	3/8" F1807 × 1/2" FSWT, 2/bag	C*	20	20
644X2	1/2" F1807 × 1/2" FSWT	B	100	1000
644X2PK2	1/2" F1807 × 1/2" FSWT, 2/bag	C*	20	20
644X32	1/2" F1807 × 3/4" FSWT	B	50	500
644X32PK2	1/2" F1807 × 3/4" FSWT, 2/bag	C*	10	10
644X3	3/4" F1807 × 3/4" FSWT	B	50	500
644X3PK2	3/4" F1807 × 3/4" FSWT, 2/bag	C*	10	10
644X43	3/4" F1807 × 1" FSWT	B	25	250
644X34	1" F1807 × 3/4" FSWT	B	25	250
644X4	1" F1807 × 1" FSWT	B	25	250
644X4PK2	1" F1807 × 1" FSWT, 2/bag	C*	5	5



NO LEAD