SERVICE PARTS LIST

M12™ HAND VACUUM

SPECIFY CATALOG NO. AND SERIAL NO. WHEN ORDERING PARTS

REVISED BULLETIN

DATE Jan. 2015

WIRING INSTRUCTION

Milwaukee **CATALOG NO.**

0850-20

STARTING SERIAL NO.

G37A

EXAMPLE:




FIG. 1 2 3	PART NO. 42-51-0500 45-80-0350	DESCRIPTION OF PART Canister Assembly Flapper Valve/Lens/Screw Kit Lens with Screws	NO. REQ. (1) (1) (1)	NO. REQ. FIG. (1) (3,4 (1) (1) 10	NOTES These parts can be purchased together as a kit (Fig. 2) or as components parts of the Canister Assembly (Fig. 1). A clean, dry surface is essential for proper performance for any
4 5 6 7 8	49-90-1950 42-70-0058 45-76-1000 31-01-0870	Flapper Valve with Screw Dry Filter Kit Housing Connection Clip Extension Tube Utility Nozzle	(1) (1) (1) (1) (1) (1)		adhesive system. The area intended for application of any adhesive label or nameplate must be prepared by cleaning with isopropyl alcohol. The solvent is to be applied with a clean, lint free applicator and the surface allowed to dry before applying the
9	31-01-0850	Crevice Tool	(1)		label or nameplate.
10	12-20-0845	Service Nameplate (Not Shown)	(1)		
11	10-20-1103	Warning Label (Not Shown)	(1)		